MONTHLY EDITION NUMBER 27

 $ISSUED\ BY:\ COMMANDER,\ THIRTEENTH\ COAST\ GUARD\ DISTRICTOa(n)$

915 Second Avenue, Seattle, Washington 98174-1067 Telephone (206) 220-7270 FAX # (206) 220-7285

BROADCAST NOTICES TO MARINERS BNMs)

This Local Notice to Mariners (LNM) includes information concerning waterways in the Thirteenth Coast Guard District promulgated by the following broadcasts:

BNM 0669-97 to 0685-97

LIGHT LIST REFERENCE: COMDTINST M16502.6, Light List Volume VI, 1996 Edition

Electronic Bulletin Board Service: (703) 313-5910

300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

NIS watchstander, 24 hours a day at (703) 313-5900

INTERNET ADDRESS

HTTP://www.navcen.uscg.mil

or

FTP://ftp.navcen.uscg.mil

I. SPECIAL NOTICE

WASHINGTON - LA PUSH - QUILLAYUTE RIVER - Entrance Flood Lights Established -

The Entrance Flood Lights have been restored to operation. These lights will be operated upon request. Users must contact Coast Guard StationQuillayute to activate the flood lights.

Chart 19480

WASHINGTON - LA PUSH - QUILLAYUTE RIVER - WATERWAY ANALYSIS - Request for Comments - The Coast Guard is conducting an analysis oQuillayute River (Light List Number 16075 to 16110) to evaluate the adequacy of the aids to navigation. Users of this waterway are invited to comment on the current system. All comments should be received by 25 July 1997 by: LCDRSchmitt, 3115 240h Ave NE, Redmond, WA 98053.

WASHINGTON - PUGET SOUND - WHIDBEY ISLAND - DIFFERENTIAL GLOBAL POSITIONING SYSTEM (DGPS) SITE - Off Air -

The DGPS site at Whidbey Island will be off air from 1000 local until 1400 local on 08 July 1997. The alternate period is 1000 local until 1400 local 09 July 1997. Mariners are reminded to use alternate means of navigation during this period.

WASHINGTON - PUGET SOUND - POINT ROBINSON - DIFFERENTIAL GLOBAL POSITIONING SYSTEM (DGPS) SITE - Off Air -

The DGPS site at PointRobinson will be off air from 0900 local until 1300 local on 15 July 1997. The alternate period is 0900 local until 1300 local 16 July 1997. Mariners are reminded to use alternate means of navigation during this period.

 $WASHINGTON - GRAYS \ HARBOR - SCRIPPS \ INSTITUTION \ OF \ OCEANOGRAPHY \ AND \ U.S. \ ARMY \ CORPS \ OF \ ENGINEERS - Deployment \ of \ Waverider \ research \ buoy \ -$

A deep water wave measurement Waverider) buoy has been deployed in approximate position 46 degrees 51.44 minutes north, 124 degrees 14.66 minutes west, in 22 fathoms. This buoy is a 3 foot diameter yellow sphere with

an attached telemetry whip antenna and a night time yellow flashing light. The light timing sequence is a series of 5 flashes at 1 second intervals with a period of 20 seconds between each series, and a visual range of 1 kilometer. The buoy is marked "WAVE BUOY" with the phone number 619-534-3032.

PACIFIC OCEAN - OREGON - NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION (NOAA) - Temporary Buoy Deployment -

A data collection buoy will be established in approximate position 45 degrees 57 minutes north, 130 degrees 0 minutes west. This buoy will be orange and white, showing a Fl W (3) 3s. The buoy will be on station for approximately one year.

Chart 501

CANADA - REGULATORY REQUIREMENTS FOR FOREIGN COMMERCIAL FISHING VESSEL ENTERING CANADIAN WATERS -

The Coastal Fisheries Protection regulations were amended 16 July 1996 to introduce new requirements for foreign commercial fishing vessels. Department of Fisheries and Oceans is reminding affected parties that these requirements are still in effect.

Please be advised that masters of foreign commercial fishing vessels must, as soon as reasonably possible, after entering Canadian waters:

- 1. Notify the Department of Fisheries and Oceans of the name, flag, state, location, route and destination of the vessel and of the circumstances under which it entered Canadian fisheries waters.
- 2. Ensure that all fishing gear on board the vessel is stowed below deck or otherwise removed from the place where it is normally used for fishing and placed where it is not readily available for fishing, and
- 3. Where requested by a Protection Officer, proceed to a specified location so that a vessel inspection can be conducted

These requirements do not apply to foreign fishing vessels operating under a Canadian fishing license. In addition, they do not apply to United States sport fishing vessels conducting normal sport fishing activities.

Affected vessel masters can notify Department of Fisheries and Oceans on the following Marine Communications and Traffic Service channels 71, 11, or 22A. At that time, fishery officials will advise if a vessel inspection is required and provide information on gear stowage.

The primary reason for the requirements is conservation. Failure to comply with requirements is viewed as a serious offense. The Coastal Fisheries Protection Act specifies a maximum penalty of \$100,000.

WASHINGTON - PUGET SOUND - EAGLE HARBOR Remediation Project -

Remediation work will take place East and West of the two piers located at the Washington State Ferries Eagle Harbor Repair Facility. Work will commence 16 June 1997 and continue through September 1997. Five marker buoys with "KEEP OUT" signs on them will be positioned around the work area. There will be derrick barges and material barges on the project site for the duration of the project. Barge mooring lights will be displayed on corners of the barges at night time. VHF-FM Channel 16 will be monitored during the working hours of 0700 to 1900, Monday through Friday, the call sign is "WPR5640".

Chart 18445, 18449 and 18474

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

I. SPECIAL NOTICE (continued)

WASHINGTON - PUGET SOUND - Submerged Instrument Deployment -

Submerged instruments will be deployed in approximate position 47²44'44.0"N 122²24'23.0"W from 20 May until 15 July 1997. This array will be marked with a 3 foot white buoy with a quick flashing yellow light. The submerged instruments will be on the bottom of Puget Sound.

WASHINGTON - PUGET SOUND - HEIN BANK - HARO STRAIT - ROSARIO STRAITHydrographic Survey

-

The Pacific Hydrographic Party will be conductingly drographic survey operations in Puget Sound from the Strait of Juan De Fuca near Hein Bank into Haro Strait up to False Bay and into Rosario Strait up to the north end of Lummi Island. Survey operations are scheduled to begin the week of 16 June 1997 and last for approximately two years. Mariners may contact the survey vessel on VHF-FM Channels 16 or 13 and are asked to keep clear during survey operations. Any person with knowledge of chart deficiencies which should be investigated during this survey may contact the Chief of Party at:

Pacific Hydrographic Party National Ocean Service, NOAA P.O. Box 189 Anacortes, WA 98221

Voice: 360-293-5171 Fax: 360-293-8456

Charts 18400, 18421, 18423, 18424, 18427, 18429, 18430, 18433, 18434, 18440, 18441, 18465, and 18471.

II. DISCREPANCIES - DISCREPANCIES CORRECTED

THE FOLLOWING AIDS TO NAVIGATION ARE NOT WATCHING AS ADVERTISED IN THE LIGHT LIST VOLUME VI, THIRTEENTH DISTRICT SECTION:

• Underlined text denotes new discrepancy since last LNM.

FEDERAL AIDS

0604-
1329-
27/97
0555-
0623-
0623-
18531
0623-
18531
18531
18531
18531

12130	BONNEVILLE POOL BUOY 69	SUBMERGED		18531		
0641-97	25/97					
12745	LAKE UMATILLA BUOY 75	SUBMERGED	18539	0646-		
97 26/97						
12755	LAKE UMATILLA BUOY 77	SUBMERGED	18539	0646-		
97 26/97						
15040	OSWEGO ROCK DAYBEACON 12	MISSING		18528		
0683-97	27/97					
15190	WILLAPA BAY ENTRANCE BUOY 8	MISSING	MISSING			
0036-97	02/97					
15585	POINT CHEHALIS RANGE FRONT L	LIGHT IMPROPER CHARAC	IMPROPER CHARACTERISTIC			
18502 0430	97 15/97					
15615	GRAYS HARBOR SOUTH REACH A	RR LIGHT MISSING TOP	DAYBO	ARD		
1850	2 0416-97 15/97					
15965	JOHNS RIVER DAYBEACON 3	DAYBOARDS MISSIN	iG			
18502 0536-	97 20/97					
18850	LACONNER RANGE FRONT LIGHT	18 MISSING		18427		
0198-95	08/95					
19005	CAP SANTE DAYBEACON 3	DESTROYED	18427	0537-		
97 20/97						

PRIVATE AIDS

LL#	Aid Name	Status Chart	BNM	LNM	
17535	POIN'	T HUDSON MAR	INA LIG	HT	TEMP DISCONTINUED
18441	0450-97	16/97			

NOTE: Mariners are cautioned that portions of missing structures may remain. THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE BEEN CORRECTED SINCE THE LAST LOCAL NOTICE TO MARINERS:

FEDERAL AIDS

LL#	Aid Name Status Chart BNM LNM			
09935	CLATSOP SPIT LIGHTED BELL BUO	Y 8 RESET ON STATION	18521	0660-
97	27/97			
11340	GOVERNMENT ISLAND SOUTH CH	DBN 11 DISCONTINUI	ΞD	
18531	0674-97 21/97			
11345	GOVERNMENT ISLAND SOUTH CH	DBN 13 DISCONTINUI	ΞD	
18531	0675-97 21/97			
11350	GOVERNMENT ISLAND SOUTH CH	DBN 14 DISCONTINUI	ΞD	
18531	0676-97 21/97			
11355	GOVERNMENT ISLAND SOUTH CH	DBN 15 DISCONTINUI	ΞD	
18531	0677-97 21/97			
11366	MC GUIRE ROCK DBN 20	DISCONTINUED	18531	0679-
97	21/97			
20285	FORT PECK LAKE LIGHT G	MISSING	00000	NONE
SENT	49/96			

PRIVATE AIDS

LL # Aid Name Status Chart BNM LNM NONE

III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED

LEGEND: TRUB = Temporary Unlighted Buoy


TRLB = Temporary Lighted Buoy TRLT = Temporary Light

THE FOLLOWING AIDS TO NAVIGATION HAVE BEEN TEMPORARILY CHANGED:

LL # 09285	Aid Na	me WINCH	Status ESTER		BNM BR ENT	LNM FRANCE	DBN 1		TRUB		18584	1322-
96	49/96									4000.0		
09315 09520		UMPQL SIUSLA		_	_	DBN 14	TRLB	TRUB	18584	1329-9	18583	49/96 0238-
96 09560	08/96		\\/ DI\/E	ED CU V	NINIEL I) V D E A	CON 26		TRUB			18583
0351-96	6	09/96	VV KIVE	EK CHA	NINEL I	JATOEA	CON 26		IKUB			10000
09856 32/95		GARIBA	ALDI CH	HANNEL	_ LT 14		TRUB			18558	0953-9	5
	/IPORAI	RY CHAN	IGES -	TEMPC	RARY	CHANG	ES CORI	RECTE) (Cont	inued)		
LL#	Aid Na	me	Status	Chart	BNM	LNM						
11365 0674-96		GOVER 19/96	NMEN	T ISLAN	ID SOU	TH CH	DBN 19		TRUB			18531
16790		SHILSH		AY BRE	AKWA	TER LIG	HT 3	SOUNI	O SIGNA	AL DISC	ONTINU	IED
18446 19005	1315-9	6 CAP SA	48/96 .NTE D	AYBEA	CON 3		TRUB			18427	0550-9	7
20/97		3 0 1			200						2000 0	-
		NG TEMI		CONTI		VIGATION	ON HAVE	EITHE	R BEEN	RESTO	RED TO)
NONE	Alu INa	IIIE	Sialus	Grian	DIVIVI	LINIVI						

IV. CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.



Corrective Object of corrective

Position

action action

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

18445 26th ed., 06/03/95 LAST LNM 18/97 NAD 83 WA - PUGET SOUND - (CGD13)27/97

POSSESSION SOUND TO OLYMPIA INCLUDING HOOD CANAL

Add Blake Island Line Mooring System Lighted Buoy (3)

Label: Mooring Cable (3) Fl Y 2.5s. Connect with magenta shaded line.

47 33'39"N 122 30'26"W to inclusive Priv maint) 47232'38.0"N122230'23.0"W

(Supersedes LNM 14/97)

18449 16th ed., 05/04/96 LAST LNM 14/97 NAD 83 WA - SEATTLE TO BREMERTON (CGD13)27/97

Add Blake Island Line Mooring System Lighted Buoy (3)

Label: Mooring Cable (3) Fl Y 2.5s Connect with magenta shaded line.

47 33'39"N 122 30'26"W to inclusive Priv maint) 47232'38.0"N 122230'23.0"W

(Supersedes LNM 14/97)

18474 5th ed., 03/25/95 LAST LNM 18/97 NAD 83 WA - PUGET SOUND - (CGD13)27/97

SHILSHOLE BAY TO COMMENCEMENT BAY

Add Blake Island Line Mooring System Lighted Buoy (3)

Label: Mooring Cable (3) Fl Y 2.5s Connect with magenta shaded line.

47 33'39"N 122 30'26"W to inclusive Priv maint) 47232'38.0"N 122230'23.0"W

(Supersedes LNM 14/97)

18521 62nd ed., 02/03/96 LAST LNM 26/97 NAD 83OR & WA - COLUMBIA RIVER - (CGD13)27/97

PACIFIC OCEAN TO HARRINGTON POINT

Change Lewis & Clark River Buoy 9 to

Lewis & Clark River Buoy 5 46209'50.0"N

123251'23.8"W

Lewis & Clark River Buoy 11 to Lewis & Clark River Buoy 7

46²09'39.5"N 123²51'18.8"W

(CGD13)27/97

Delete Lewis & Clark River Buoy 10 46209'43.8"N

123251'23.2"W

18531 18th ed., 02/19/94 LAST LNM 26/97 NAD 83 OR & WA - COLUMBIA RIVER - (CGD13)27/97

VANCOUVER TO THE DALLES

Delete Government Island South Channel Daybeacon 11

45234'16.2"N 122232'16.6"W

Government Island South Channel Daybeacon 13 45²34'05.3"N

122231'27.4"W

Government Island South Channel Daybeacon 14 45²34'07.0"N

122230'33.0"W

Government Island South Channel Daybeacon 15 45233'50.2"N

122229'20.8"W

Government Island South Channel Daybeacon 19 45233'36.1"N

122227'43.6"W

Mc Guire Rock Daybeacon 20 45²33'35.5"N

122227'24.0"W

V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

WASHINGTON - RICH PASSAGE Buoyage -

During the month of July 1997, the bell will be removed from ainbridge Reef Lighted Bell Buoy 4 (LLNR 18030). No other changes will occur.

Chart 18441

VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

Comments may be sent to the address on page one of this Local Notice to Mariners.

NONE

VII. GENERAL

DREDGING IN PROGRESS OR PLANNED WITHIN THE I¹³COAST GUARD DISTRICT. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION AND REDUCE THEIR WAKE WHEN TRANSITING THESE AREAS:

Location Area Start Complete Chart Grays Harbor Cow Point 03/09/97 08/14/97 18502

FISHERIES/BIOLOGICAL SAMPLING, PIER CONSTRUCTION, HYDROGRAPHIC SURVEYS, ETC., CURRENTLY IN PROGRESS WITHIN THE 1th COAST GUARD DISTRICT. ALL MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN TRANSITING THESE AREAS:

Location Area Start Complete Type of Work

Lake Washington Evergreen Floating Bridge 06/01/97 06/30/97

Maintenance work

Lewiston Idaho Snake River 05/15/97 07/15/97 Scheduled maintenance

Lk. Wash. Ship Canal Fremont Bridge 05/06/97 08/30/97 Scheluled Maintenance

Tacoma Blair Waterway 01/28/97 To Be Announced 11th St. Bridge

Demolition

Snohomish River State Route 529 Bridges 05/06/97 To Be Announced

Replacement of old lift cables

WASHINGTON - PUGET SOUND - Marine Events - Puget Sound Area -

AREA/LOCATION DATE TIME EVENT SPONSOR PHONE #
Guemes Island 07/09/97 1830-2200 Sail Boat Race Anacortes YC 293-5134

Commencement Bay 07/09/9 Meadow Pt 07/09/97 1919	97 1800-: 1800-2100				Windseekers ian YC of Seattle		07 789-
West Point/Point Wells 07/10/9 789-1919	97 1600-2	2100	Sail Bo	at Race	Corinthian YC o	of Seattle	Э
Alki Point/West Point 07/11/9 Port Ludlow/Double Bluff/Klas F 437-0814			Sail Bo 1030-1		Seattle YC Sail Boat Race	325-100 Port Lu	
Lake Washington/Stan Sayers Cup USA 820-6373	Pit 07126	/97	0930-1	730	Dragon Cup		Dragon
Bellingham Bay 07/12/97 1693	1600-2000	Sail Bo	at Race	Belling	ham Ethells Flee	ŧt	676-
Meadow Point/point Wells Seattle 789-1919	07/13/97	1000-2	000	Sail Bo	at Race Corinth	ian YC d	of
Bellingham Bay 07/13/97 1693	1600-2000	Sail Bo	at Race	Belling	ham Ethells Flee	t	676-
Meadow Point/West Point 783-2589	07/14/97	1815-2	100	Sail Bo	at Race Sloop T	avern Y	C
Meadow Point/Point Wells Seattle 789-1919	07/14/97	1000-2	000	Sail Bo	at Race Corinth	ian YC d	of
Meadow Point/Point Wells Seattle 789-1919	07/15/97	1000-2	000	Sail Bo	at Race Corinth	ian YC d	of
Guemes 07/16/97	1830-2200		at Race	Anacor	tes YC 293-513	34	
Commencement Bay 07/16/9					Windseekers		
Meadow Point 07/16/97 1919	1800-2000				ian YC of Seattle		789-
Meadow Point/Point Wells	07/16/97	1000-2	000	Sail Bo	at Race Corinth	ian YC c	of
Seattle 789-1919 West Point/Point Wells 07/17/9	97 1600-	2100	Sail Bo	at Race	Corinthian YC o	of Seattle	e
789-1919 Meadow Point/Point Wells	07/17/97	1000-2	000	Sail Bo	at Race Corinth	ian YC c	of
Seattle 789-1919 Meadow Point/Point Wells	07/18/97	1000-2	000	Sail Bo	at Race Corinth	ian YC c	of
Seattle 789-1919 Bowman Bay Anacortes 07/20/9	97 1100-	1300	Jet Ski	Run	Skagit Power S	norte	757-
7999 Port Ludlow/Snake Rock					_	•	
0814	07/21/97	1400-2			at Race Port Lu		437-
Guemes Island 07/23/97							
Commencement Bay 07/23/9	97 1800-2	2200	Sail Bo		Windseekers		
Port Ludlow/Klas Rocks 07/26/9		1600			Port Ludlow YC		
Fort Peck MT 07/27/97 Dyes Inlet/Silverdale 07/27/9 282-3644					reek Marina Silverdale Whal	485-250 ling Days	
Ketron Island/Steilacom 07/29/9 478-8155	97 1200-	1600	Rowing	Contes	t Tahoma Outdoo	or Pursu	its
Guemes Island 07/30/97	1830-2200	Sail Bo	at Race	Anacor	tes YC 293-513	34	
Commencement Bay 07/30/9		2200			Windseekers		07
Meadow Point 07/30/97 1919	1800-2100	Sail Bo	at Race	Corinth	ian YC of Seattle	e	789-
West Point/Point Wells 07/31/9 789-1919	97 1600-:	2100	Sail Bo	at Race	Corinthian YC o	of Seattle	Э
OREGON - Marine Events - Port	land Area -						
	TIME EVEN	Т	SPON	NSOR	PHONE	E #	

OREGON - WASHINGTON - COLUMBIA RIVER - COLUMBIA RIVER CHANNEL RIVER MILE 74 - Lost Anchor -

The Coast Guard has been advised that, on 28 January 1997 a merchant vessel lost a 10.5 ton anchor in the Columbia River Channel. The vessel reportedly lost the anchor in the center of the channel at River Mile 74. According to ArmyCorp of Engineer charts, the recorded depth in this area is 50 feet.

Chart 18524

WASHINGTON - GRAYS HARBOR - COW POINT TO CENTER OF CROSSOVER CHANNEL - Dredge Operations -

Dredging operations have commenced from Cow Point to the center of Crossover Channel. These operations will be 24 hours per day, 7 days a week and will continue until 14 August 1997. The vessels involved are the Derrick Barge VIKING, Towboat WOLLOCHET, and the Towboat MARIE M. The operating vessels will monitor VHF-FM Channels 13 and 16. Properdayshapes and lights will be displayed during these operations.

Chart 18502

WASHINGTON - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The drawspan of the following Ship Canal bridges need not open for the passage of vessels at the following dates and times this month:

Montlake

June 140830-1000 1200-1300 1330-1430 1600-1700 June 210730-0830

University

June 21 0800-0900

Chart 18447

VII. GENERAL (Continued)

WASHINGTON - PUGET SOUND - SNOHOMISH RIVER - Bridge Information -

The dual vertical lift span bridges across the Snohomish River at Everett on State Route 529 are unable to open for the passage of vessels until the old lift cables are replaced. The drawbridges will remain in the closed position until further notice.

Charts 18443 and 18444

WASHINGTON - PUGET SOUND - LAKE WASHINGTON SHIP CANAL - Bridge Information -

The Fremont Bridge need not provide double-leaf openings for the passage of vessels unless one hour notice is provided Monday through Friday from 0600 local to 2200 local and from 0700 local to 2200 local on Saturday from 06 May to 30 August 1997, except for Memorial Day and 04 July. The painting of the bridge will occasionally require the placement of containment material beneath the Bridge which may reduce vertical clearance by as much as three feet.

Chart 18447

WASHINGTON - TACOMA HARBOR - BLAIR WATERWAY - Bridge information -

The 11th Street Bridge is being demolished. The center span lights are extinguished but the pier protection lights will remain operational until the structure is removed. The drawspan will be maintained in the open position until removed. Floating equipment will move out of the channel as needed for the passage of vessels.

Charts 18453 and 18474

WASHINGTON - SNAKE RIVER - Two Mooring Buoys Deployed -

Two mooring buoys were established upstream of Lower Granite Lock and Dam. One is on the south side of the river approximately 150 yards from the south shore in approximate position 46²39'08.4"N 117²24'29.5"W. The other is approximately 150 yards off the north shore in approximate position 46²39'25.9"N 117²24'24.4"W. These mooring buoys will remain until mid summer.

Chart 18547

VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1996:

AND	PACIFIC ISLA	ANDS 19	96:						
ØØØØø	risk *, indicates the c ØØØØØØØØØØØØØ ØØØØØØØØØ							rmation added. ØØØØØØØØØØØØØØØØØØØØØ	
(1) No.	(2) (3) (4) Name and location Remarks			(7) Charac	(8) cteristic	Ht	Rng	Structure	
	Government Island	l South Char	nnel						
11340	- Daybeacon 11 27/97					Remov	ve from I	ist.	
11345	- Daybeacon 13 Remove from list. 27/97							st.	
11350	- Daybeacon 14 27/97			Remove from list					
11355	- Daybeacon 15 27/97					Remov	e from li	st.	
11365	- Daybeacon 19 27/97				SG on	pile.		Remove from list.	
•	McGuire RockDayb 27/97 wis and Clark River	peacon 20						Remove from list.	
14595	- Buoy 5 46 09.8			Green	can.				
123 5	1.4 27/97								
14600	- Buoy 10					Remov	e from li	st	

• 27/97

14605 - Buoy 7 46 09.7 Green can.

123 51.3

• 27/97 Quillayute River

16095 - ENTRANCE LIGHT 3 47 54.5 Obscured on rangeline. Flood 124 38.7

structure as Quillayute

15

4 SG on pile. On same

illuminate the entrance

lights

Island

and the Jetty. The lights will be energized upon request to Coast Guard StationQuillayute River.

River Direction Light.

channel between James

IX. ADDITIONAL ENCLOSURES:

If you have any questions, comments, or need additional information concerning this or othen the LNM Mailing List (e.g. additions, deletions, corrections) contact the address or phone number on the front page.

FIG 4s

G. F. GREENE

Commander, U.S. Coast Guard Chief, Aids to Navigation & Waterways Management Branch Thirteenth Coast Guard District By direction of the District Commander